

## TriFoiler Engineering Change Notices

Assembled, sequenced, and PDFed by:  
Jonathan Levine (jonathan@canuck.com)  
TF#23

Editor's note:

The observant reader will discover that there is duplication between some of these documents. This was a completist's conscious choice. In organizing them, I chose to remain true to the chronological order of issuance rather than purging redundant material. To do otherwise risks confusing anyone who later comes across the "removed" portions.

The "ECN" designations are mine. In all other respects these documents are as received. I hope you find this useful.

ECN01\_TIP                      October 7th, 1994

- Adjusting the ride height
- Inspecting the steering cable
- Mast caution

ECN02\_FIX2                    July 6th, 1995

- Hobie merger announcement
- Sensor bow line
- Overhead wire caution
- Rudder holdup clip
- Handling caution

ECN03\_TIP3                    August 21st, 1995

- Adjustable shock absorbers

ECN04\_MAST-ROT              October 17th, 1995

- Mast rotator upgrade

ECN05\_AMA-FOAM              October 17th, 1995

- Ama reinforcement

ECN06\_FIX3                    October 19th, 1995

- Main beam rivet upgrade

- Sensor rising discussion

ECN07\_OW-MN-UD            November 3rd, 1995

Owner's manual update:

- Backstay tension
- Compression strut upgrade
- Sensor bow line
- Adjustable shock absorbers
- Foil plates

ECN08\_OW-MN-U2            February 22nd, 1996

Owners manual update:

- Backstay tension
- Compression strut upgrade
- Sensor bow line
- Adjustable shock absorbers
- Foil plates

ECN09\_TIP4                 May 1st, 1996

- Tuning tip: Sail link length

ECN10\_OW-MN-U3            May 8th, 1996

Owners manual update:

- Hard turn caution
- Walking the beam caution
- Derigging mast caution
- Rudder drop caution

ECN11\_FIX4                 May 13th, 1996

- Reinforcing the main hull under the speedo
- Reinforcing main sheet turning block mounting
- Steering cable blocks caution
- Sensor modification
- Sail link length recommendation
- King post hook caution
- Sitting caution
- New manual announcement

ECN12\_FIX5                      May 24th, 1996

- Sensor bow line adjustment
- King post hook caution
- Sitting caution
- New manual announcement

ECN13\_OW-MN-U4                June 10th, 1996

Owners manual update:

- Mast stepping
- Beaching and launching

ECN14\_FIX6                      June 18th, 1996

- Main hull reinforcement under beam
- Reinforcing ama bows
- Foil lock-down hook roll pins caution

ECN15\_TIP5                      August 13th, 1996

- Steering cable warning
- New video manual announcement
- Rudder shear pin upgrade

ECN16\_FIX7                      September 17th, 1996

- Lower gudgeon transom reinforcement

ECN17\_FIX8                      March 3rd, 1997

- Compression strut U-bracket upgrade

ECN18\_LEEBOARD                June 5th, 1997

- Leeboard announcement

ECN19\_SHOCK2                  October 15th, 1998

- Rebuilding shock absorber

ECN20\_Leeboard\_info          February 25th, 1999

- Leeboard announcement